



The Coal
Authority

Resolving the **impacts** of mining



British
Geological
Survey

Ground Stability Non-Residential Report



WOODFIELD SCHOOL STONELEIGH ROAD SITE,
STONELEIGH ROAD, COVENTRY, CV4 7AB

Date of enquiry:	19 January 2024
Date enquiry received:	19 January 2024
Issue date:	19 January 2024

Our reference:	61004299533001
Your reference:	60277485

Ground Stability Non-Residential Report

This report is based on and limited to the records held by the Coal Authority and the records and geological interpretation of the British Geological Survey (BGS) at the time the report was produced.

Client name

NLIS

Enquiry address

WOODFIELD SCHOOL STONELEIGH ROAD SITE,
STONELEIGH ROAD, COVENTRY, CV4 7AB


How to contact us

0345 762 6848 (UK)
+44 (0)1623 637 000 (International)

200 Lichfield Lane
Mansfield
Nottinghamshire
NG18 4RG

www.groundstability.com

 /company/the-coal-authority
 /thecoalauthority
 /coalauthority



Approximate position of property



Reproduced by permission of
Ordnance Survey on behalf of
HMSO. © Crown copyright and
database right 2018. All rights
reserved.

Ordnance Survey Licence number: 100020315

Coal Authority Summary

Has the search report highlighted evidence or potential of		
1	Past underground coal mining	No
2	Present underground coal mining	No
3	Future underground coal mining	No
4	Mine entries	No
5	Coal mining geology	No
6	Past opencast coal mining	No
7	Present opencast coal mining	No
8	Future opencast coal mining	No
9	Coal mining subsidence	No
10	Mine gas	No
11	Hazards related to coal mining	No
12	Withdrawal of support	No
13	Working facilities order	No
14	Payments to owners of former copyhold land	No

BGS Summary

Has the search report highlighted evidence or potential of		
1	Shrinkable clay	Yes
2	Running sand	No
3	Deposits which could compress	No
4	Deposits which could collapse	No
5	Natural landslide activity	Yes
6	Soluble rocks	No

Detailed findings from the Coal Authority

1. Past underground coal mining

The property is not within a surface area that could be affected by any past recorded underground coal mining.

2. Present underground coal mining

The property is not within a surface area that could be affected by present underground mining.

3. Future underground coal mining

The property is not in an area where the Coal Authority has received an application for, and is currently considering whether to grant a licence to remove or work coal by underground methods.

The property is not in an area where a licence has been granted to remove or otherwise work coal using underground methods.

The property is not in an area likely to be affected from any planned future underground coal mining.

No notices have been given, under section 46 of the Coal Mining Subsidence Act 1991, stating that the land is at risk of subsidence.

4. Mine entries

There are no recorded coal mine entries known to the Coal Authority within, or within 20 metres, of the boundary of the property.

5. Coal mining geology

The Coal Authority is not aware of any damage due to geological faults or other lines of weakness that have been affected by coal mining.

6. Past opencast coal mining

The property is not within the boundary of an opencast site from which coal has been removed by opencast methods.

7. Present opencast coal mining

The property does not lie within 200 metres of the boundary of an opencast site from which coal is being removed by opencast methods.

8. Future opencast coal mining

There are no licence requests outstanding to remove coal by opencast methods within 800 metres of the boundary.

The property is not within 800 metres of the boundary of an opencast site for which a licence to remove coal by opencast methods has been granted.

9. Coal mining subsidence

The Coal Authority has not received a damage notice or claim for the subject property, or any property within 50 metres of the enquiry boundary, since 31 October 1994.

There is no current Stop Notice delaying the start of remedial works or repairs to the property.

The Coal Authority is not aware of any request having been made to carry out preventive works before coal is worked under section 33 of the Coal Mining Subsidence Act 1991.

10. Mine gas

The Coal Authority has no record of a mine gas emission requiring action.

11. Hazards related to coal mining

The property has not been subject to remedial works, by or on behalf of the Coal Authority, under its Emergency Surface Hazard Call Out procedures.

12. Withdrawal of support

The property is not in an area where a notice to withdraw support has been given.

The property is not in an area where a notice has been given under section 41 of the Coal Industry Act 1994, cancelling the entitlement to withdraw support.

13. Working facilities order

The property is not in an area where an order has been made, under the provisions of the Mines (Working Facilities and Support) Acts 1923 and 1966 or any statutory modification or amendment thereof.

14. Payments to owners of former copyhold land

The property is not in an area where a relevant notice has been published under the Coal Industry Act 1975/Coal Industry Act 1994.

Detailed findings from BGS

1. Shrinkable clay

The property is in an area underlain by clay. Clay can swell or shrink if the moisture content changes.

However, the clay deposits in this area are considered to be mainly of "low plasticity". This means it is unlikely that they will cause ground movement.

2. Running sand

The property is not in an area underlain by running sand.

3. Deposits which could compress

The property is not in an area underlain by deposits which could compress and cause ground movement.

4. Deposits which could collapse

The property is not in an area underlain by deposits which could collapse and cause ground movement.

5. Natural landslide activity

The property is in an area where the local geology and steepness of slope could increase the likelihood of landslide activity.

It is however unlikely to occur unless substantial changes are made to the ground or the surrounding vegetation, this includes excessively wet weather.

6. Soluble rocks

The property is not in an area underlain by soluble rocks.

Comments on the BGS information

These features should not necessarily give cause for concern.

Whether or not a property is affected by ground movement can depend on a number of factors such as its age, type of construction, and on its surroundings and such matters as drainage and nearby trees.

Since 1992 buildings should have been designed and constructed according to buildings regulations to ensure natural ground movement will not cause damage to a building.

However, you should consider the possible consequences before you:

- carry out any building or excavation work
- alter the ground surface or drainage of surface or ground water
- plant or remove large shrubs or trees

Ground movement can cause uneven damage or subsidence to a property.

Developers should always carry out an appropriate risk assessment before starting any work on, or around, a property.

If you own the property and it is damaged by ground movement: You should contact your insurance company and anyone else who has an interest in the property, for example, the mortgage lender.

If you are considering buying the property and BGS has identified that ground movement could occur you should tell your professional advisers.

Additional remarks

This report has been prepared in accordance with the Law Society's Guidance Notes 2018, the User Guide 2018 and the Coal Authority and the British Geological Survey's Terms and Conditions applicable at the time the report was produced. The information provided by the Coal Authority has been compiled in response to the Law Society's CON29M Coal Mining enquiries and is protected by copyright owned by the Law Society of 113 Chancery Lane, London WC2A 1PL.

Disclaimer

The Coal Authority and British Geological Survey owns the copyright in this report and the information used is protected by our database rights. All rights are reserved and unauthorised use is prohibited. If we provide a report for you, this does not mean that copyright and any other rights will pass to you. However, you can use the report for your own purposes.

Alternative formats

If you would like this information in an alternative format, please contact our communications team on 0345 762 6848 or email communications@coal.gov.uk.



Terms and conditions

Our full terms and conditions can be found on our website – www.groundstability.com.

Enquiry boundary

Key

Approximate position of enquiry boundary shown



How to contact us

0345 762 6848 (UK)
+44 (0)1623 637 000 (International)

200 Lichfield Lane
Mansfield
Nottinghamshire
NG18 4RG

www.groundstability.com

 /company/the-coal-authority

 /thecoalauthority

 /coalauthority



Reproduced by permission of Ordnance Survey on behalf of HMSO. © Crown copyright and database right 2018. All rights reserved.

Ordnance Survey Licence number: 100020315

General information

This report has been prepared by the Coal Authority using the information held by the Authority, together with information supplied by the British Geological Survey (BGS).

1. The Coal Authority and the British Geological Survey (BGS) are referred to in the report as the suppliers.
2. This report is confidential and has been prepared specifically for the property and for use by the owner only. It should not be relied upon by any other property or by any other third party.
3. The report is based on and limited to:
 - a. the specific features identified in the report
 - b. each suppliers interpretation of the records it holds relating to the particular features for which the report states that the supplier is responsible at the time the report is prepared
4. The records used do not represent an exhaustive or comprehensive list of all the records that may exist or may be available for the property. No physical inspection of the property has or will be carried out in the preparation of this report.
5. Information from the Coal Authority is based on records in its possession relating to coal mining activity. There may be information held by others on historical coal mining, and information on other types of mining, which is not searched for as part of this report.
6. Information from BGS relates solely to the 6 natural ground stability hazards as described in this report. It does not cover any other geological hazards or man-made hazards (such as contaminated land). BGS may hold data on other geological hazards and features that may affect the property which are not searched for as part of this report. Consequently the report should not be taken as a guarantee that there are no other geological hazards or other issues affecting the property. For a more detailed interpretation please visit the BGS's website www.bgs.as.uk
7. Information from BGS is prepared using the BGS GeoSure database which is based on 1:10,000 scale geological mapping reduced to 1:50,000 scale.

8. The information from suppliers may be derived from records from a number of disparate sources which vary in age, quantity and quality. Such records may include material donated to the suppliers from third parties, which may not have been subject to any verifications or other quality control process.
9. Raw data used to prepare this report may have been transcribed from analogue to digital format, or may have been acquired by means of automated measuring techniques. Consequently, some data may have been processed without human intervention and may contain undetected errors.
10. The records available to the suppliers are constantly being updated. The suppliers cannot be held responsible for any changes in the information on which this report is based which occur after the date the report was produced.
11. If this report is for a residential property, insurance is included. This report includes a policy and key facts summary which outline the significant features, benefits and limitations of the cover provided. Full terms and conditions are shown in the policy document.
12. The report gives an indication of whether ground movement could occur at the property. This does not necessarily mean that the property is or will be affected by ground instability. Such an assessment can only be made by inspection of the property by a qualified professional, such as a surveyor or engineer. This report does not therefore –
 - include any information or warranty relating to the actual state, or the structural or other condition, of the property
 - determine the saleability or value, or the safety, of the property
 - indicate the suitability of the property for any particular purpose (including, without limitation, its suitability for development (within the meaning of section 55 of the Town and Country Planning Act 1990 as amended) or any building, excavation or landscaping work)
 - act as a substitute for any physical inspection, specialist interpretations and/or professional advice